FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

) DC	IIIICO	wy	tere			- Table		-		
	(Re	: G.	O. Ms.	20/70/	PWD	Dt.	23 -	01	-1970)	-

Name of the School	iii - 31 .	:	Vyasa	V	idya	Ni kethan	Central
					Asok	Kumaa	K.A, AE
1. Name of the Officer							

	Location		Poteachisa,	Chalabudi
4.	Location			

3.	Period for which the certificate is issued		2022 - 23	
	m Chailding		permanent	structure

4.	Types of building	•	permanent	31740004
_	N of defeat if any			

5.	Nature of defect if any	: ₁		GF - 1298.73 m2
	a) Foundation and basement	:		FF - 1294.57 m2
	b) Superstructure			SF - 1366.87m2
	c) Doors and windows			- 1386.8743
	d) Wood work wrought and put up	: \	Nil	

d) Wood work	wrought and put up	•
e) Roof		:
f) Flooring		

	done properly	The structure is sound for conduc
8.	Whether the structure is sound or not for conducting classes	claves under normal wind & wea
	Contacting contact	conditions

1. The stability of the structure should be examined also with reference to location Note:altitude intensity of wind exposure or flood etc.

2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

CERTIFICATE

Certified that the School was inspected by me on _______28 | 5 | 2022 and found to be fit / unfit to conduct classes for the period ... 16. 2022 21/3/2023 for the reason stated above.

Date: 28/5/2022

True copy out

PHO TOC

Assistant Engineer ASSISTANT ENGINEER MUNICIPAL OFFICE CHALAKUDY

School

, LID FEW

SREENIVASAN M.K. PRINCIPAL

VYASA VIDYANIKETHAN CENTRAL SCHOOL CHALAKUDY - 680307

U. PRABHAKARAN . MANAGER VYASA VIDYANIKETHAN CENTRAL SCHOOL CHALAKUDY - 680 307

PH: 0480 - 2707316